

Environment Testing

Eurofins Auburn Laboratory Report

Maine Coast Laboratory
47 Gardiner Road
Wiscasset, ME 04578

Job ID: 295-20687-1
Date Received: 9/24/2026 7:30 AM
Sample Collected In: Maine
Job Desc: White Tail Ridge
Association

The analytical test results presented in this report meet all requirements of the associated regulatory program listed in the Certification Summary section, unless otherwise noted. This certificate shall not be reproduced, except in full, without the written approval of the analyzing laboratory. The results presented in this report relate to the samples listed on the following pages in the condition in which they were received. Data qualifiers and/or narrative comments are included to explain any exceptions, if applicable. Regulated compliance samples (e.g. SDWA, NPDES) must comply with associated agency requirements/permits.

Receipt

The sample was received on 9/24/2026 7:30 AM. Unless otherwise noted below, the sample arrived in good condition, and, where required, properly preserved and on ice. The temperature of the cooler at receipt time was 7.0°C.

Certification Summary

Certifications for this job are presented below. Note that not all certifications may be applicable to your report and certifications for subcontracted laboratories are available upon request. Analytes not considered to be certified under the certifications associated with this report will have an asterisk next to their names. Evidence of certification for laboratories within Eurofins Environmental Testing can be found on the following website: <https://www.eurofinsus.com/environment-testing/resources/certifications/>

Eurofins Auburn (AUB), 155 Center Street, Building C, Auburn, ME 04210

Maine, Lab ID: ME01076

Maine (Rad), Lab ID: SPC20, RSP50083

Action Limit Summary

Sample results for 295-20687-1 have been evaluated against the following action limits and/or Maximum Contaminant Levels:

- EPA Primary Limits: Maine EPA Primary DW MCL
- EPA Secondary Limits: Maine EPA Secondary DW MCL
- State Limits: 295 - Maine - Guidelines

Definitions regarding the evaluations presented within this report are presented below:

- EPA Primary Limits: Legally enforceable standards known to affect human health.
- EPA Secondary Limits: Non-enforceable standards that may cause cosmetic or aesthetic effects.
- Pass: Result is below the action limit and/or MCL.
- Fail: Result is above the action limit and/or MCL.
- Attention: Result indicates a potential pathway for contaminants to enter the system that warrants investigation.
- No Limit: No action limit or MCL is available.

Analysis Related Notes


DF: "Dilution factor" means the ratio of the volume of the final (dilution) solution to the volume of sample.

MDL: "Minimum Detection Limit" means the minimum result which can be reliably distinguished from a blank with predetermined confidence level.

ND: Non-detected at the reporting limit (or MDL or EDL if shown).

RL: "Reporting limit" means the lowest level of an analyte that can be accurately recovered from the matrix of interest.

Data qualifier flags provide additional information in regards to the receipt, analysis or quality control of a sample. If any such flags are associated with the results of this report, they will be listed below along with their definitions.



CERTIFICATE OF ANALYSIS FOR DRINKING WATER

CLIENT SAMPLE ID:	TP-1 EP (TP-1 FOR 203' WELL)	SYSTEM NAME:	White Tail Ridge Association
SAMPLE ID #:	295-20687-1		
CLIENT JOB #:			
OTHER SAMPLE INFO:	Pumphouse		
SAMPLED BY:	Mike Harvey		
PWSID:	ME0098233		
COLLECTION DATE/TIME:	09/22/26 10:15		

Test Description (SM7500_Rn_B)	Results	Units	Pass/ Fail	DQ Flag	RL	DF	Limit	Analyst /Lab	Date & Time Prepared	Date & Time Analyzed
Radon	<100	pCi/L	✓		100	1	4000	HP - AUB		09/24/26 17:37

Maine Drinking Water Program RADON-3RD QUARTER

Please read the enclosed sampling instructions before collecting sample(s)

Frequency: Quarterly

Loc: 295
20687
#1 A
Radon



95-20687 COC

3

Public Water System Information		Laboratory Information	
System Name:	WHITE TAIL RIDGE ASSOCIATION	Laboratory Name	Eurofins-Auburn
System Phone #:		Lab Certification:	ME01076
PWSID Number:	ME0098233	Lab Director:	Rebecca Labranche
Address:	80 BEN HALE ROAD	Lab Phone #:	(207) 784-5354
	WATERFORD, ME 04088		
Sample Category:	RT	On Ice:	☒ ~~NX~~ Laboratory use ONLY
System Type:	COMMUNITY	Initial Temp	7 °C Corrected Temp 579
Samplers Name:	HARVEY, MICHAEL	DELIVERY:	WALK IN ☐ MAIL ☐ UPS/FED EX ☐ COURIER ☒ DROP BOX ☐
	WQ & C	Paid:	S Bill: ☒ S ☐ Check# ☐ CC

Required Analysis: RADON-3RD QUARTER

of Samples: 1

Is your system chlorinated? Yes ☒ No ☐ For chlorinated samples please circle FREE or TOTAL. Default value will be FREE.

#	Sample Point	Sampling Location (Per DWP Schedule)	Collection Point	Date & Time Sample Taken	Field Measurements	Comments
					Chlorine mg/L	Temp °C
						pH
1	TP-1	TREAT PT 1		9/22/26		
		EP (TP-1 FOR 203' WELL)	TP1 - Pump house	10:15	14.8	8.3

I/We understand this report will be submitted to the Maine Drinking Water Program.

Relinquished by Sampler:	M/Kedhney	Date	9/22/26	Time	1530
Relinquished by:	R	Date	9/22/26	Time	1530
Relinquished by:		Date		Time	
Received by:	R	Date	9/22/26	Time	1530
Received by:		Date		Time	
Received by Laboratory:	MF	Date	9/24/26	Time	1530